


Xi3000 Bluetooth Scanner

Below you will find setup instructions for your scanner. Please follow these instructions below to connect the cables and to power up the scanner. All settings have been **configured** for the scanner to work properly with The Uniform Solution. For additional setup information, review the document [xi3000-bt.doc](#) located on the CD that came with your scanner.

Powering up the Xi3000-BTStand


The computer should be turned off prior to connecting any cables to your computer.



Connect the interface cable into the 15-pin connector at the back of the base then plug the other end of the cable into **an available USB port** on the computer. Connect the power supply provided to your AC outlet and plug the other end into the base then power on the computer.

Powering up the Xi3000-BT Scanner

Located the battery in the box with the scanner. Insert the battery into the bottom of the scanner and lock into place by pushing the clip to power on the scanner. The scanner will beep and the LED will be on when power the scanner is powered on.




The manufacturer is advising if you are not going to be using the scanner for prolonged periods of time, then you should remove the battery from the scanner.

Charging the Xi3000-BT


You can charge the battery 3 way different ways. 1) You can place the scanner on the base, 2) insert the battery in the base or 3) connect the power supply into the DC Jack at the bottom of the scanner.

Scanner



Place the scanner with the battery inserted on the base to charge. It will take approximately four (4) hours to charge the battery, and when fully charged, the LED will be a solid RED.

Battery



The power adaptor must be connected to charge the battery. Insert the battery in the front of the base to charge. It will take approximately four (4) hours to charge the battery and when fully charged, the LED will be a solid GREEN.