



HHP IT3800 Scanner – USB Interface

Read these instructions before connecting the scanner to your computer.

1. The computer should be **ON**. Close any open programs.
2. Removed the scanner and the USB cable from the box
3. Connect the USB cable to the scanner and to an available USB port on your computer.
4. Download and print out the HHP IT3800 Setup document. Make sure you print the setup document on a good Inkjet or Laserjet printer. Read and follow the steps as outlined in the document. Place the Setup Sheet on a flat surface and scan the UPC's in the order listed on the setup sheet. When setup is complete, open The Uniform Solution program > Invoice and scan the USW and/or the UPC barcodes into the invoice to validate it function.