



## AML M2002 Scanner/Decoder – Keyboard Connection

**Read these instructions before connecting the AML Scanner/Decoder M2002 to your computer.**

The decoder box does not require a power supply it is powered by the computer. Do not plug any cables into the decoder box while the computer is on. You can cause sever damage not only to the decoder box, but also to other hardware. **The Uniform Solution program does not use the drivers provided by the manufacturer.** The CD should only be used to view the User's Guide.

### Connecting the adapter cables to the Decoder box and to the Computer

1. The computer should be **Off**.
2. In the box with the decoder are three (3) adapter cables. One (1) long cable and two (2) short cables.
  - Connect one of the short cables to the long cable then connect the long cable to the port on the decoder box labeled **Computer**. Plug the other end of the cable into the **Keyboard** port on the back of the **computer**.
  - Connect the other short cable to the port on the decoder box labeled **Keyboard** then plug the keyboard into the other end of this cable.
3. Connect the Scanner to the decoder box.
4. Turn the comptuer **ON**.
5. The Uniform Solution program should be closed.
6. Download and print out the AML M2000/M6300 Decoder Setup document. Make sure you print the setup document on a good Inkjet or Laserjet printer. Read and follow the steps as outlined in the document. Place the Setup Sheet on a flat surface and scan into an open notepad document to verify your results. When setup is complete, you may test the scanner by scanning The USW and/or the UPC barcodes into the notepad to validate it function.